

Sticklers™ CleanWipes™ 640

Optical Grade Cleaning Wipes

Product Features:

- Cleans dust, dirt, fingerprints and moisture in a single pass
 - Lint-free optical grade wipes clean LC & SC Simplex, Duplex, ST, FC & MPO connectors
 - Eight color-coded CleanSwipe™ slots prevent accidental cross contamination with multiple connector end-faces
 - Electrostatic-dissipative cleaning surfaces prevent charging when wiping connector end-faces
- Cleans bare fibers prior to cleaving & splicing
- Designed to clean 640 connector end-faces or 100 bare fibers for fusion splicing
 - Rugged plastic box keeps wipes clean and dry

TYPICAL CLEANING APPLICATIONS:

- Carrier Networks
- Enterprise Networks
- Cable Assembly Production
- R&D and Test Labs
- Network Installation Kits



Video:
How to Use:
CleanWipes

@ SticklersCleaners.com

Cleaning slots feature a tight pitch to clean both end-faces on duplex connectors with one swipe.




For best results, use with:

Sticklers™ Fiber Optic Splice & Connector Cleaner
Part Number: MCC-POC03M



PACKAGING:

Part Number	MCC-WCS640
Contents	80 Wipes / 640+ Clean
Package Dimensions	8.6cm L x 8.6cm H x 6.4cm H 3.4" L x 3.4" H x 2.5" H
Wipe Dimensions	2" x 4.25" (5.08cm x 10.8cm)
Case Dimensions	227 mm L x 178 mm W x 178 mm H 9" L x 7" W x 7" H
Case Quantity	12 CleanWipes Boxes/Case
GHS/HCS Pictogram	Not Applicable
Recycle Symbol*	

*Per: 94/62/ EC and 97/129/EC

Sticklers™ CleanWipes™ 640 Conforms to the Following Fiber Optic Industry Standards:

INDUSTRY STANDARDS	SECTION	DESCRIPTION
ANSI/TIA 455-240 2009		Fiber Optic Connector End-Face Cleaning Evaluation
ANSI/TIA 568.3D-2016 ARINC	E.3.5	Connector End-Face Cleaning
805-4 ARINC 806-5 AT&T ATT-TP-76461 Cisco Systems Doc: 51834 IBM SY27-2597-15 IEC 61300-3-35 IEC 61627-1 IEC 62627-1 IPC 8497-1 IPC 8497-1		Fiber Optic Test Procedures
IPC 8497-1 NASA-STD 8739.5A	5.3	Fiber Optic Installation & Maintenance
SAE AIR6031 SAE ARP 6283 SAE ARP 6283 Telcordia GR2923	9.2	Inspecting & Cleaning End-Faces
CORE Issue 2 Telcordia GR765-CORE Verizon VZ.TRP.9461	7.8	Inspecting & Cleaning Procedures for Fiber Connectors
	7.3.2	Cleaning End-Faces for Maintaining Fiber Links
	7.3.3	End-Face Cleaning
	10.8	Basic Procedure for Wet-Dry Cleaning
		Acceptable Wet-Dry End-Face Cleaning
		Dry Wipes and Cassette End-Face Cleaning
		Wet-Dry Cleaning of End-Faces
		Minimizing Electrostatic Charge Effect
		Cleaning Workmanship Standards
		End-Face Cleaning
	8.2	Approved Lint Free Dry Wipes
	9.1.1	Wet-Dry Wipe Cleaning
		End-Face Cleaning
	4.6	Materials & Consumable Criteria
	5.0	End-Face Cleaning